

PILOT BOARDING DEFICIENCY REPORT

DATE:	2/12/2020 TIME:1130
VESSEL	: Al Qibla
MASTE	R:
PILOT:	M. P. Haley
CONDI	TIONS: Calm
APPLIC	ABLE LADDER ARRANGEMENTS (check all that apply):
	PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER
DEFICIENCIES (check all that apply and provide brief comment)	
	GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
	PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
	Ladder not properly secured from strong point on deck to side ropes. Deck tongue in use.
	COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
	MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
	DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
	ONAL REMARKS: ing method hidden under platform. Looked underneath saw deck tongue as only means of securing
All the	weight of ladder is resting on the one step. Explained to crew.
See	picture.
Signatu	re:

