

## PILOT BOARDING DEFICIENCY REPORT

DATE: _	2/12/2020 TIME:	
VESSEL	Al Qibla	
MASTE		
PILOT:	M. P. Haley	
CONDI	TIONS: Calm	
APPLIC	ABLE LADDER ARRANGEMENTS (check all that apply):	
	PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER	
DEFICIE	ENCIES (check all that apply and provide brief comment)	*
_	GENERAL ARRANGEMENT (ie: Insufficient lighting, no office	er, unsafe deck access, etc.)
	PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)	
	Ladder not properly secured from strong point or	n deck to side ropes. Deck tongue in use.
	COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)	
	MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)	
	DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigg	ing, etc.)
	ONAL REMARKS: ring method hidden under platform. Looked underneath	saw deck tongue as only means of securing
All the	e weight of ladder is resting on the one step. Explained	to crew.
See p	picture. M.V. AL QIBLA	
Signatu	VALLETTA CALL SIGN: 9HA3958 GRT: 141077 NRT: 75570 BHP: 37575	LOT M