



PILOT BOARDING DEFICIENCY REPORT

DATE: JAN 13, 2020 TIME: 17:20

VESSEL: ANDIMILOS

MASTER: _____

PILOT: SALVADOR RIVAS

CONDITIONS: WINDS 10 KTS EAST SEAS - 2-3 EAST-N-E

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER (STARBOARD SIDE)
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

POOR CONDITION OF RUNGS AND ROPES. (WAS NOT ABLE TO GET PICTURE DUE TO DARKNESS)

☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

1) BOTTOM MOST STEP WAS BROKEN AND NOTHING PREVENTING ONE SIDE FROM FALLING OUT

2) RIGHT SIDE OF LADDER LOWER THAN LEFT RUNGS WERE NOT EVEN


3) VARIOUS STEPS HAD DAMAGE. ONCE I STEPPED ONTO THE PILOT BOAT PIECE OF WOOD FROM LADDER FELL ONTO DECK OF MOTORBOAT

Signature: _____


MASTER (if available)

PILOT

BLACK CORNERS
ON RUNS ON
BOTTOM STEP
MISSING. NOTHING
PREVENTING STEP
FILM COMING OUT
OF SLICE



NOT ACTUAL CAMERA (PICTURE USED
TO DESCRIBE DEFICIENCY)



NOT ACTUAL LADDER
PICTURE TO SHOW
HOW LADDER RUNGS
WERE NOT EVEN