



PILOT BOARDING DEFICIENCY REPORT

DATE: 2/9/2020 TIME: 2130

VESSEL: Atlantic breeze

MASTER:

PILOT: M. P. Haley

CONDITIONS: Moderate NW'ly

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Ladder not properly secured from strong point on deck to side ropes.

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Crew used shackles to secure side ropes directly to the strong point. The result is the shackle rides

To the step and all the weight of ladder is resting on the one step. Explained to captain and crew.

See picture.

Signature: _____

MASTER (if available)


PILOT

