

PILOT BOARDING DEFICIENCY REPORT

DATE:	9/2/18 TIME: 1300
VESSEL	: ATLANTIC CROWN
MASTE	R:
PILOT:	SALVADOR RIVAS
CONDI	FIONS: LIGHT EASTERLY WINDS + SEAS
APPLIC	ABLE LADDER ARRANGEMENTS (check all that apply):
	PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER
DEFICIE	NCIES (check all that apply and provide brief comment)
	GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
	PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
	COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
	BOLTS HOLDING GANGWAY RAILS LECUTED BY WIRES NOT NUT
	MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
_	
П	DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
ADDITIO	DNAL REMARKS:
	TICED WHILE DISEMBARKING USED STARBOARD GANGWAY
NOT	COMBINATION (PILOT DECISION) BOLTS HOLDING TRAILS ON BOTH SIDE
MIS	SING LOT NUTS & BOTH WERE SECURED BY WIRE (SEE PICTURE).
Signatu	re:
	MASTER (if available) PILOT

