



PILOT BOARDING DEFICIENCY REPORT

DATE: 4/15/18 TIME: 19:30

VESSEL: BW KESTREL

MASTER: _____

PILOT: Paul Klein

PILOT: MAUL KIKIM
CONDITIONS: PORT BEARING SOUTH ROCK 5/5/10

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT

☒ OTHER CANAWAY (SEE P125)

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

70° ANGLE

ADDITIONAL REMARKS:

ADDITIONAL REMARKS:

✓ VERY DANGEROUS CLIMB,
✗ TRANSITION FROM GANTRY TO STEPS ON SHIP
WAS NOT SAFE.

Signature: _____

MASTER (if available)

PILOT