

PILOT BOARDING DEFICIENCY REPORT

DATE: 5 28 18 TIME: 0800 VESSEL: CHALLENGE PROCYON
MASTER:
PILOT: FOLEY
CONDITIONS:
APPLICABLE LADDER ARRANGEMENTS (check all that apply):
☐ PILOT LADDER ONLY ☐ COMBINATION LADDER ☐ SIDE PORT ☐ OTHER
DEFICIENCIES (check all that apply and provide brief comment)
GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
□ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.) □ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
PITCH of PORTABIE GANGWAY EXCESSIVE.
ADDITIONAL REMARKS:
THE PORTABLE GANGWAY WAS RIGGED AT AN ANGIE THAT FAR
EXCEEDED ITS DESIGNED SAFE ANGLE. THE TIMY TREADS WERE
INADEQUATE AT SUCH AN ANGLE.
B-Q
Signature:

PILOT

MASTER (if available)



