



PILOT BOARDING DEFICIENCY REPORT

DATE: 2/18/18 TIME: 0200

VESSEL: Cont Equator

MASTER: _____

PILOT: W Speiser

CONDITIONS: clear, icy, snow on gangway

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Gangway

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

gangway set at dangerous angle; see below

ADDITIONAL REMARKS:

Attempted to climb snow-covered gangway and when
nearing the top, the gangway made cracking noises. The
crew implored me to stop and go back down. Top of
gangway overhung deck by 4-5 feet.

Signature: _____

W Speiser

MASTER (if available)

PILOT

(see photos)





