



PILOT BOARDING DEFICIENCY REPORT

DATE: 10 MARCH 2020 TIME: 1310

VESSEL: MSC CARMEN

MASTER: _____

PILOT: RIVAS

CONDITIONS: S. SWELL 4 FT SE WIND 15

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

STEP OFF PLATFORM HAD A REPAIR CONSISTING OF

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)


- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

RUSTED METAL PLATES WITH SCREWS. NOT ALLOWED
PER IMO. FULL REPLACEMENT STEP MUST BE
USED. CAPTAIN NOTIFIED BY VHF AFTER DISEMBARKING

Signature: _____

MASTER (if available)


PILOT

