

PILOT BOARDING DEFICIENCY REPORT

DATE: 9/5/19 TIME: ~1830
VESSEL: MSC PAOLA
MASTER:
PILOT: SAL TRIVAS
CONDITIONS: WINDS 30KTS SEAS - 6FT
APPLICABLE LADDER ARRANGEMENTS (check all that apply):
☐ PILOT LADDER ONLY ☐ COMBINATION LADDER ☐ SIDE PORT ☐ OTHER
DEFICIENCIES (check all that apply and provide brief comment)
☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
BOLTS TO HANDRAILS HELD BY ROPE NO NUTS
DOUTS TO HANDRAILS HELD BY ROPE NO NUTS MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
ADDITIONAL REMARKS: (SEE PICTURES)
Signature:

MASTER (if available)

PILOT



