



PILOT BOARDING DEFICIENCY REPORT

DATE: 9 FEB 2020 TIME: 1630

VESSEL: MIRELLA S

MASTER: _____

PILOT: SALVADOR RIVAS

CONDITIONS: WINDS <5 KTS (SOUTH) (NOSWELL)

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☒ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

BOTTOM RUNG METAL PLATE GOING THRU STEP. 2ND FROM

☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

BOTTOM STEP CRACKED & BROKEN. TOP & SECOND STEP MISSING
RUBBER SPACERS ON TOP OF STEP. I REFUSED TO CLIMB THE
LADDER CREW BROUGHT STARBOARD LADDER (IN GOOD CONDITION) TO
PORT SIDE. SHIP HAS ONE GOOD LADDER

Signature: _____

MASTER (if available)

[Signature]
PILOT









