



PILOT BOARDING DEFICIENCY REPORT

DATE: 2/12/2020 TIME: 1900

VESSEL: Noble Ace

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Calm


APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☒ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Ladder not properly secured from strong point on deck to side ropes. Shackled directly to side 

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Only shackles used to secure directly to side ropes. Shackles ride up to the step

All the weight of ladder is resting on the one step. Explained to captain and crew.

See picture.

Signature: _____

MASTER (if available)

PILOT

