



PILOT BOARDING DEFICIENCY REPORT

DATE: 3/29/19 TIME: ~1807

VESSEL: UNDINE

MASTER: _____

PILOT: SALVADOR RIVAS III

CONDITIONS: _____

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

POOR CONDITION OF GANGWAY

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)


- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

AT SOMEPOINT GANGWAY WAS DAMAGED, STEPS ARE AT ANGLES OR BENT, WHOLE GANGWAY IS WARPED. WIRES FOR GANGWAY ARE IN WAY OF HANDROPES. (SEE PHOTO)

Signature: _____

MASTER (if available)



PILOT

