



PILOT BOARDING DEFICIENCY REPORT

DATE: 02/19/2020 TIME: 1430

VESSEL: Anton Schulte

MASTER: _____

PILOT: Dominic Vitolo

CONDITIONS: NW 25 Kts SE Swell 6' long period

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
Trap door configuration not rigged properly

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

See Pics. Pilot ladder secured beneath the platform. Second pilot ladder secured to the top of the platform but behind the grab bars.

~~Thank~~

Signature: _____

MASTER (if available)

Dominic Vitolo

PILOT

