



PILOT BOARDING DEFICIENCY REPORT

DATE: 6/18/20 TIME: 2200

VESSEL: CHESAPEAKE HIGHWAY

MASTER: _____

PILOT: RIVAS

CONDITIONS: _____

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☒ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

4TH STEP FROM BOTTOM PORT SIDE BENT (NEEDS TO BE REPLACED)

☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Signature: _____

MASTER (if available)

PILOT

RIVAS



