



PILOT BOARDING DEFICIENCY REPORT

DATE: 2/16/2020 TIME: 0215

VESSEL: Cornelia Maersk

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Light-moderate SSW'ly

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Ladder not properly secured from strong point on deck to side ropes. Not independent of ladder.

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

No deck Strong point available to secure ladder independent of the ladder reel. Ladder reel only method of securing.

Ladder not secured to strong point on deck. Not independently secured from ladder reel

Explained to captain and crew. See pictures.

Signature: _____

MASTER (if available)

[Signature]
PILOT



