



PILOT BOARDING DEFICIENCY REPORT

DATE: 9 September 2019 TIME: 1300

VESSEL: Dank Silver

MASTER: _____

PILOT: E.A. Miller

CONDITIONS: Fair, NW 10-15 kt

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

☐ PILOT LADDER ONLY

☐ COMBINATION LADDER

☐ SIDE PORT

☒ OTHER

Ship's portable gangway at berth

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

Severe angle, pivoting on a piece of wood on dock.

ADDITIONAL REMARKS:

This ship was in ballast condition. The gangway was too steep to climb. It was also unstable. The wood planks it had been riding on had shifted as the ship lightered causing the gangway to pivot and swing in an unsafe manner.

Signature: _____

MASTER (if available)

PILOT

E.A. Miller E.A. Miller





