

## PILOT BOARDING DEFICIENCY REPORT

DATE: 04/26/20 TIME: 1800	
DATE: 04/26/20 TIME: 1800 VESSEL: Libra Leader	-
MASTER:	_
PILOT: Salvador Rivas	_
CONDITIONS: East swell 7ft and North winds	-
APPLICABLE LADDER ARRANGEMENTS (check all that apply):	
<ul> <li>■ PILOT LADDER ONLY</li> <li>□ COMBINATION LADDER</li> <li>□ SIDE PORT</li> <li>□ OTHER</li></ul>	_
DEFICIENCIES (check all that apply and provide brief comment	
■ GENERAL ARRANGEMENT (ie: Insufficient lighting, no	officer, unsafe deck access, etc.)
unauthorized repair on lowest spreader (port	side pilot ladder)
PILOT LADDER (ie: Poor condition/wear, not resting or	hull, poor rigging, etc.)
☐ COMBINATION LADDER (ie: Poor condition/wear, not	secured, platform too low, etc.)
☐ MAN ROPES (ie: Poor condition/wear, incorrect diame	ter, poor rigging, etc.)
☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor	rigging, etc.)
ADDITIONAL REMARKS: Port side pilot ladder lowest spreader has	4 cuts in where the rope feeds thru it
was take off for a repair. Two blocks of wo	od were bolted to the bottom of the
spreader with 4 rusted bolts on each side.	
Signature:	
MASTER (if available)	PILOT