



PILOT BOARDING DEFICIENCY REPORT

DATE: 03/03/2020 TIME: 0300

VESSEL: Maersk Denver

MASTER: _____

PILOT: W. Baeszler

CONDITIONS: moderate light rain

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Trap Door

DEFICIENCIES (check all that apply and provide brief comment)

- ☒ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
officer on deck, nobody to greet by trap door
- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
when lowered came down awkwardly, cables did not lower evenly, effortlessly,
- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
plastic ladder secured to the bottom of trapdoor only, difficult to reach up to pass through trap door,
- ☒ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
N/A no man ropes
- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

once reached deck containers stacked overhead large opening to gangway with no containment i.e rope, chain, railing,

Captain mentioned when not in use while suspended from side needed securing.

Crew radioed sometime later that securing had been done. Mechanism not secure on its own.

Signature: _____

MASTER (if available)

PILOT

William J Baeszler 03/03/2020