

PILOT BOARDING DEFICIENCY REPORT

DATE:	2/17/2020 _{TIME:} 1430	
VESSEL: NY Trader 2		
MASTER:		
PILOT:	Andrew Parkis	
CONDITIONS: Clear/Calm		a a constant of the constant o
APPLICABLE LADDER ARRANGEMENTS (check all that apply):		
	PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER	
DEFICIENCIES (check all that apply and provide brief comment)		
	GENERAL ARRANGEMENT (ie: Insufficient lighting, no of	ficer, unsafe deck access, etc.)
		an and a second an
	■ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)	
	Poor Condition, Climb exceeded 9m	
	COMBINATION LADDER (ie: Poor condition/wear, not se	cured, platform too low, etc.)
	MAN ROPES (ie: Poor condition/wear, incorrect diameter	er, poor rigging, etc.)
_		
	□ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)	
ADDITIONAL REMARKS: Ladder needs to be replaced before next boarding		
Signatu	re:	A.J. PARKETS
	MASTER (if available)	PILOT

