



PILOT BOARDING DEFICIENCY REPORT

DATE: 5/5/2020 TIME: 1430

VESSEL: Palena

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Light NW'ly wind

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Trap Door

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Ladder not resting on hull. Ladder fixed to underside of rail. Not to "height of handrail"

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Ship constructed in 2006. Ladder not rigged "through the trap door" fixed to underside of lower rail and not to "height of handrail" ladder not flat

Against hull. Capt. stated he already notified company. Not scheduled for dry dock until Dec 2021

Explained to captain and crew. See pictures and report from 3/31/2020

Signature: _____

MASTER (if available)

PILOT



PILOT BOARDING DEFICIENCY REPORT

DATE: 3/31/2020 TIME: 1430

VESSEL: Palena

MASTER:

PILOT: M. P. Haley

CONDITIONS: Light-mod NE'ly wind E'ly swell

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Trap Door

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Ladder not resting on hull. Ladder fixed to underside of rail. Not to "height of handrail"

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Ship constructed in 2006. Ladder not rigged "through the trap door" fixed to underside of lower rail and not to "height of handrail" ladder not flat

Against hull. Capt. stated he already notified company. Not scheduled for dry dock until Dec 2021

Explained to captain and crew. See pictures.

Signature: _____

MASTER (if available)

PILOT







