



PILOT BOARDING DEFICIENCY REPORT

DATE: 3/28/2020 TIME: 0345

VESSEL: Wide Bravo

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Light NE'ly wind long low S'ly swell

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Trap Door

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Ladder not resting on hull. Ladder not "rigged through" trap door.

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Ship constructed in 2014. Climb on ladder is obstructed by yellow bar where the ladder runs behind therefore the ladder is not

"Rigged through" the trap door. Refused to use. Ship unable to rig any other combination config.

Explained to captain and crew. See pictures.

Signature: _____

MASTER (if available)

Signature: _____
PILOT









