



PILOT BOARDING DEFICIENCY REPORT

DATE: 11/8/2020 TIME: 1900

VESSEL: Agios Dimitrios

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Light airs low swell

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Trap door then regular Combination

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

After reconfigured, ladder was secured on main deck to railing, large step from ladder to g'way

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Trap door configuration not compliant to current standards.

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Ladder not passing through trap door. Ladder not secured to height of handrail. Ladder not resting

Against hull. Ladder and g'way not secured to hull. Denied boarding. Crew reconfigured to

"Traditional" combo. Gap from ladder to g'way was large. Ladder secured to ship handrail.

Signature: _____

MASTER (if available)

PILOT









