



PILOT BOARDING DEFICIENCY REPORT

DATE: 12/10/2020 TIME: 1830

VESSEL: MSC Athens

MASTER:

PILOT: M. P. Haley

CONDITIONS: Light-moderate w'ly wind. No swell

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☒ SIDE PORT
- ☐ OTHER

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

(Stbd side) Broken chocks. Stretched side ropes. Crooked steps. Secured via "deck tongue"

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Noticed broken chock on 1 crooked step from pilot boat. As I climbed there were multiple crooked steps and Side ropes seemed stretched around chocks on other steps. Noticeable repairs made. Ladder Secured @ top via deck tongue and not side ropes. Sideropes fatigued Ladder should be replaced

Signature: _____

MASTER (if available)

PILOT

