



# PILOT BOARDING DEFICIENCY REPORT

DATE: 9/8/21 TIME: 2300

VESSEL: AS Petra

MASTER: \_\_\_\_\_

PILOT: JP Britton

CONDITIONS: Winds: S 25 kts Sea: 2 M

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER \_\_\_\_\_

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Rope ladder does not continue beyond the platform. Painting of railings non compliant.

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Was not able to discuss with the master, as this was a departure.

Signature: \_\_\_\_\_

MASTER (if available)

JP Britton  
PILOT



