



PILOT BOARDING DEFICIENCY REPORT

DATE: 30 Oct 2021 TIME: 1345

VESSEL: Argolikos

MASTER: _____

PILOT: E. A. Miller 032

CONDITIONS: ESE swell 6', SSE wind 10-15 KT

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER Trap Door

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Framework to trap door overlapped rope ladder. Ladder not centered.

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

The left side rope of the ladder was in a metal bracket from the frame of the trapdoor. This caused the hardware to overlap with the rope ladder, allowing access to the right half of the rope pilot ladder. The captain was informed on the radio of the poor rigging.

Signature: _____

CAF 032

MASTER (if available)

PILOT







