



PILOT BOARDING DEFICIENCY REPORT

DATE: 4/16/2021 TIME: 2300

VESSEL: Challenge Passage

MASTER:

PILOT: M. P. Haley

CONDITIONS: Moderate NW'ly wind. Light rain

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER Ships portable gangway

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

Gangway pitch very steep.

ADDITIONAL REMARKS:

Very steep portable gangway going to dock. Exceeding the maximum 30° design angle. "Steps"

Are insufficient for use with that much angle especially being wet from rain. See Pictures.

Signature: _____

MASTER (if available)

PILOT







