

## PILOT BOARDING DEFICIENCY REPORT

DATE: 3/17/2021 TIME: 1800
VESSEL: Hafnia Phoenix
MASTER:
PILOT: M. P. Haley
CONDITIONS: Light NE'ly wind.
APPLICABLE LADDER ARRANGEMENTS (check all that apply):
<ul> <li>□ PILOT LADDER ONLY</li> <li>■ COMBINATION LADDER</li> <li>□ SIDE PORT</li> <li>□ OTHER</li> </ul>
DEFICIENCIES (check all that apply and provide brief comment)
■ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
No officer
PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
Ladder improperly secured to deck
COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
ADDITIONAL REMARKS: Ladder not secured to strong point on deck. Only to platform holding the ladder reel (see pictures) ladder crooked during climb (not
Pictured) no qualified officer on deck to inspect ladder and receive pilot. Only ships cadet.
Crew was able to rectify and secure ladder to deck for next time as there are strong points available.
Signature:



