



PILOT BOARDING DEFICIENCY REPORT

DATE: Feb 14, 2021 TIME: 0330

VESSEL: MOL GLIDE

MASTER: _____

PILOT: R.J. DREXER

CONDITIONS: NE 10-15kts, SEA 4FT, temp 32°F

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

TRAP DOOR WITH CROSS BAR in the way

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS: Capt and OWNERS AWARE TRAP DOOR needs to be corrected. Capt
gave pilot copy of plans for modifications APPROVED BY
ABS (CLASSIFICATION society) Capt stated he hopes OWNERS WILL

HAVE MODIFICATIONS MADE IN A FEW MONTHS.


Signature: _____

MASTER (if available)


PILOT

R.J. DREXER







<STORAGE & HORIZONTAL CONDITION>



<HANDRAIL ASSEMBLY CONDITION>



<PILOT EMBARKATION CONDITION>



REVIEWED

Details of this review are as indicated in the ABS letter



<STORAGE & HORIZONTAL CONDITION>

<HANDRAIL ASSEMBLY CONDITION>

#4

"A" VIEW

REMOVE CROSS-BEAM
UNLIKE EXISTING PLATFORM.

IT NEED TO ASSEMBLE HANDRAIL
ON NEW PLATFORM BY CROFT

"B" VIEW

RECTANGULAR HOLLOW
CONSTRUCTION HANDRAIL

<PILOT EMBARKATION CONDITION>

UPPER DECK

"C" VIEW

THERE IS NO OBSTACLE FOR
PILOT EMBARKATION.

REVIEWED

Details of this review
are as indicated in the
ABS letter

