



PILOT BOARDING DEFICIENCY REPORT

DATE: 2/11/2021 TIME: 1106 disembarking

VESSEL: Maersk Denver

MASTER: C. Rumrill

PILOT: Christine Razukas

CONDITIONS: cloudy

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER trap door

DEFICIENCIES (check all that apply and provide brief comment)

- ☒ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

officer was on deck, he did not follow me down accommodation ladder.

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

An additional bar/handle was welded on - see picture attached

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

difficulty to get a good hold of top opening of trap door. Ladder did not pass through. It ended at trap door.

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

N/A

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

N/A

ADDITIONAL REMARKS: Please see attached photos.

When I inquired about the trap door, the captain assured me that the magnet would be on. He also said that he lists the ship so the ladder rests against the hull. When disembarking, no magnet and I waited until it was put on.

Signature: _____

MASTER (if available)

Christine Razukas

PILOT









