

PILOT BOARDING DEFICIENCY REPORT

DATE:	7/23/2021 TIME: 0200	
VESSEL	Maersk Kensington	
MASTE	R:	
PILOT:	M. P. Haley	
CONDI	IONS: Ligh'ly wind.	
APPLIC.	ABLE LADDER ARRANGEMENTS (check all that apply):	
· 🗆	PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER Trap door configuration	
DEFICIE	NCIES (check all that apply and provide brief comment)	
	GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)	
	PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)	
	Not resting flat against the hull. Ladder not secured to height of handrail.	
	COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)	
	Gangway not secured to hull. Ladder not passing through trap door.	
	MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)	
	DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)	
	ONAL REMARKS: ed to board this vessel.	
Signatu	re:	
	IVIASTER (II available) PILOT	

