



# PILOT BOARDING DEFICIENCY REPORT

DATE: 3/8/2021 TIME: 1600

VESSEL: Maersk Serangoon

MASTER: \_\_\_\_\_

PILOT: M. P. Haley

CONDITIONS: Light-moderate w'ly wind. No swell

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER \_\_\_\_\_

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Trap door on stbd side as backup. Second accom ladder on stbd side not working

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

## ADDITIONAL REMARKS:


Trap door rigged on stbd side as backup. Other accom Ladder used for traditional combo configuration unable to be use

Due to malfunction. Refused trap door and used port side combination ladder. Capt says stbd will be

Fixed prior to sailing. Should be confirmed before leaving port.

Signature: \_\_\_\_\_

MASTER (if available)

  
PILOT





