



## PILOT BOARDING DEFICIENCY REPORT

DATE: 10/7/2021 TIME: 0600

VESSEL: SCF Prime

MASTER:

PILOT: M. P. Haley

CONDITIONS: Ligh'ly wind.

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Poor rigging

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Crew tied pilot ladder to handrails. (See pics) Strong points on deck were available. Had crew properly tie off

Ladder to strong points.

Signature: \_\_\_\_\_

MASTER (if available)

PILOT



