



## PILOT BOARDING DEFICIENCY REPORT

DATE: August 5, 2021 TIME: 0600

VESSEL: Zhong An Xin Hua Yuan

MASTER: Capt. Wu Xiang

PILOT: J.P. Britton

CONDITIONS: Easterly wind/seas 1M/15-20 knots

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER \_\_\_\_\_

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)  
\_\_\_\_\_
- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)  
\_\_\_\_\_
- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)  
Trap door arrangement. Ladder does not go through platform as required. Not secured to hull
- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)  
\_\_\_\_\_
- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)  
\_\_\_\_\_

ADDITIONAL REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Signature: \_\_\_\_\_

MASTER (if available)

James R  
PILOT



