

PILOT BOARDING DEFICIENCY REPORT

DATE: 11/16/2020 TIME: 0700	
VESSEL: AGOS DIMITRIOS	
MASTER:	
PILOT: MARK WANDERER	
CONDITIONS: WIND/SEAS CALM	
APPLICABLE LADDER ARRANGEMENTS (check all that apply):	
PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER	
DEFICIENCIES (check all that apply and provide brief comment)	
GENERAL ARRANGEMENT (ie: Insufficient lighting, no of	fficer, unsafe deck access, etc.)
□ PILOT LADDER (ie: Poor condition/wear, not resting on	hull, poor rigging, etc.)
COMBINATION LADDER (ie: Poc. upadicion/wear, not se	cured, platform too low, etc.)
LADDER NOT SECURED TO SHIPS	DIDN'T ALIGN WITHPLATTERM CPENING
MAN ROPES (ie: Poor condition/waar, incorrect diameter	
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)	
ADDITIONAL REMARKS:	
THIS IS A RETROFIT TO THE ORIGINAL "TR	
LADDER WAS NOT SECURED TO THE SHIP AND IT NOW TALLOW WITH THE CARNING.	
THE SPREADER POSITION ON THE CROSS BAR PREJENTED ME FROM USING THE FIRST AVAILABLE RUNG ON THE LADDER IT WAS TOO CLOSE TO THE CROSS	
BAR TO GET A FOOT ON IT.	
Signature:	Markalan
MASTER (if available)	PILOT







