



## PILOT BOARDING DEFICIENCY REPORT

DATE: 10/18/2020 TIME: @ noon

VESSEL: CSE 6 Sydney

MASTER: \_\_\_\_\_

PILOT: William Blake

CONDITIONS: SE 15 kts 3 ft seas

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER trap door combination ladder.

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Platform w/ hatch canted away from ship, ladder not resting on hull

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

worst ladder of my career.

Signature: \_\_\_\_\_

MASTER (if available)

[Signature]  
PILOT