



PILOT BOARDING DEFICIENCY REPORT

DATE: OCT 30, 2020 TIME: 1900

VESSEL: MOL GLIDE

MASTER: _____

PILOT: HAROLD CAVAGNARO

CONDITIONS: E/NE 20-25 KTS 6 FT E'LY SWELL

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

LADDER NOT IN COMPLIANCE. DOES NOT PASS THROUGH TRAP DOOR.

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

LADDER ATTACHED ABOVE AND BELOW CROSS BAR AS SEEN IN PICTURE.
BOARDING WAS HAZARDOUS DUE TO THIS ARRANGEMENT.

Signature: _____

MASTER (if available)

PILOT

H. CAVAGNARO

