



## PILOT BOARDING DEFICIENCY REPORT

DATE: 5/26/21 TIME: 0800

VESSEL: Celsius Rimini

MASTER: -

PILOT: W Speiser

CONDITIONS: clear, daylight, no precipitation (dry)

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER KM1 DOCK 3

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

Gangway was excessively pitched at dangerously high angle. (see photos)

ADDITIONAL REMARKS:

Although properly netted and attended by a sailor, the gangway's  
pitch was dangerous.

Signature: (NOT AVAILABLE)

MASTER (if available)

W Speiser

PILOT



