



# PILOT BOARDING DEFICIENCY REPORT

DATE: 4/28/2021 TIME: 0600

VESSEL: Maersk Detroit

MASTER: \_\_\_\_\_

PILOT: M. P. Haley

CONDITIONS: Light S'yly wind SE'yly swell.

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER \_\_\_\_\_

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Non compliant Trap door configuration

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Trap door configuration. Ladder not passing through trap door. Ladder not resting against the hull.

Ladder not secured to height of handrail.

Signature: \_\_\_\_\_

MASTER (if available)

PILOT