



PILOT BOARDING DEFICIENCY REPORT

DATE: March 06, TIME: 1200
VESSEL: MAERSK PITTSBURGH

MASTER: _____

PILOT: Robert J Dreher

CONDITIONS: good

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
☐ COMBINATION LADDER
☐ SIDE PORT
☒ OTHER Trap door combination ladder

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

There is a bar in the way when transferring from ladder to
gangway. Captain is well aware of problem. Captain stated MAERSK
has plans to make modifications, but does not know when it will
be done.

Signature: _____

MASTER (if available)

Robert J Dreher
PILOT Robert J. Dreher



