



PILOT BOARDING DEFICIENCY REPORT

DATE: 02/11/21 TIME: 0830

VESSEL: MAERSK SERANGOON

MASTER: _____

PILOT: Ryan P. Pakalik

CONDITIONS: calm wx NE wind

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☒ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

The general arrangement was not safe, there was a wide gap to transfer
☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.) from ladder to gangway

Ladder was not secured against the hull by magnets
☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

As mentioned wide gap to transfer and there was a crew member
☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.) at the bottom of the gangway who was in the way.

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

The ladder was not secured to the hull. At the bottom of the gangway there was a crew member trying to steady the ladder. He was in the way & there was a wide distance between the ladder & gangway

Signature: _____

MASTER (if available)

PILOT



