



PILOT BOARDING DEFICIENCY REPORT

DATE: 1/25/2020 TIME: 0215

VESSEL: Unayzah

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: Fly rocks Fly swell 3-5 ft

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☒ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☒ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

Ladder not fixed to strong point via side ropes. Deck tongue in use. All weight on one step

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Deck tongue hidden under platform. Asked crew to ^{remove} ~~fix~~ to see how ladder is secured. Deck strongpoints only used to keep ladder horizontal. All weight only on one wooden step (see photos)

Signature: _____

MASTER (if available)

PILOT

[Signature]



