



PILOT BOARDING DEFICIENCY REPORT

DATE: 11/11/18 TIME: 9:30am

VESSEL: ypapanti

MASTER: _____

PILOT: Elizabeth Miller

CONDITIONS: Clear

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☒ OTHER gangway

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☒ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

@ Chevron

ADDITIONAL REMARKS:

gangway couldn't be rigged properly
due to heavy pitch. Terminal & gangway
couldn't be used

Signature: _____

MASTER (if available)

Elizabeth Miller

PILOT



