

PILOT BOARDING DEFICIENCY REPORT

DATE: 27 Mar 2020 TIME: 0600
VESSEL: Alora
MASTER:
PILOT: A. CODLING
CONDITIONS: RAZN
APPLICABLE LADDER ARRANGEMENTS (check all that apply):
PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER
DEFICIENCIES (check all that apply and provide brief comment)
☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.) VNSAFE ENBARKATZON
ADDITIONAL REMARKS: THIS IS AN ISSUE THE AGENT SHOULD HAVE RESOLVED PRIOR TO DEPARTURE.
TO GET ONBOARD I USED MILLER'S CAUNCH
Signature:
MASTER (if available) PILOT







