



PILOT BOARDING DEFICIENCY REPORT

DATE: 1/18/2020 TIME: 0115 Sailing

VESSEL: Columbine Maersk

MASTER: _____

PILOT: M. P. Haley

CONDITIONS: calm

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Pilot ladder not secured to a strong point independent of Ladder Reel

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

See pictures. Officer on Deck told it was
not compliant

Signature: _____

MASTER (if available)

PILOT

[Signature]



