



PILOT BOARDING DEFICIENCY REPORT

DATE: 03/02/2019 TIME: 0325

VESSEL: HOPA

MASTER: _____

PILOT: Ryan P. Pakalik

CONDITIONS: Broken ladder rung

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☒ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Pilot ladder rung broke while I was stepping off the ladder.

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

While stepping back towards the deck of the Pilot Launch the
third rung from the bottom broke. I fell back but landed on my feet.
I took pictures of the ladder & had the Pilot Boat log the incident.

Signature: _____

MASTER (if available)

PILOT



