



## PILOT BOARDING DEFICIENCY REPORT

DATE: 1/18/2020 TIME: 1230 Boarding

VESSEL: MSC Vigo

MASTER: \_\_\_\_\_

PILOT: M. P. Haley

CONDITIONS: calm

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☒ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☒ SIDE PORT
- ☐ OTHER \_\_\_\_\_

DEFICIENCIES (check all that apply and provide brief comment)

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Ladder not Secured to Strong point on Deck Independent of Reel

☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

See pictures Captain notified that  
it was not compliant

Signature: \_\_\_\_\_

MASTER (if available)

PILOT

M. P. Haley



