



PILOT BOARDING DEFICIENCY REPORT

DATE: DEC 03, 2020 TIME: 0730

VESSEL: ASTRID SCHULTE

MASTER: _____

PILOT: R.J. DREHER

CONDITIONS: Good vis, wind west 15 kts

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER

DEFICIENCIES (check all that apply and provide brief comment):

☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Ladder goes through TRAP DOOR, but cross bar is obstructed

☐ MAN ROPES (ie: poor condition/wear, incorrect diameter, poor rigging, etc.)

☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Signature: _____

MASTER (if available)

R.J. Dreher
PILOT

