



PILOT BOARDING DEFICIENCY REPORT

DATE: 9/7/21 TIME: 1130

VESSEL: M/V Agrolikos

MASTER: _____

PILOT: JP Britton

CONDITIONS: Calm

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☒ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Non-compliant rigging: rope ladder obstructed by trap door platform

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Disussed with the Captain and he is aware of the non-conforming attributes of the arragment.

Captain said the owners are aware and that I should be fixed in the next port.

Signature: _____

MASTER (if available)

James R
PILOT



