



PILOT BOARDING DEFICIENCY REPORT

DATE: 1/6/21 TIME: 1500

VESSEL: Sunny Bay

MASTER: _____

PILOT: Jon Flanders

CONDITIONS: NW wind - 25 kts

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☒ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☐ SIDE PORT
- ☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Poor rigging - only two small lines holding ladder - see pics

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Pics sent to NY and NJ Presidents, Apprentice Russell Stuebe was riding,

Long climb but not sure of the actual freeboard,

Signature: _____

MASTER (if available)

PILOT





